

CLECO POWER LLC BRAME ENERGY CENTER



CCR ANNUAL INSPECTION

BOTTOM ASH POND

JANUARY 2025

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1.0 GENERAL INFORMATION.....	1-1
2.0 QUESTIONS FOR OWNER’S REPRESENTATIVE	2-1
3.0 PHYSICAL DAM FEATURES - RESERVOIR.....	3-1
4.0 PHYSICAL DAM FEATURES - INTAKE WORKS.....	4-1
5.0 PHYSICAL DAM FEATURES - OUTLET WORKS.....	5-1
6.0 SLOPE PROTECTION - EXTERIOR SLOPES	6-1
7.0 SLOPE PROTECTION - INTERIOR SLOPES	7-1
8.0 SLOPE PROTECTION - ABUTMENT/TOE	8-1
9.0 SURFACE IMPOUNDMENT CREST	9-1
10.0 PHYSICAL DAM FEATURES - SPILLWAY	10-1
11.0 DOCUMENTATION REVIEW.....	11-1

LIST OF APPENDICES

Appendix

- A Photograph Log
- B P.E. Certification

SECTION 1.0

GENERAL INFORMATION

ANNUAL CCR SURFACE IMPOUNDMENT INSPECTION			
Facility Name:		Cleco Brame Energy Center	
Address:		275 Rodemacher Rd. Lena, LA	
Surface Impoundment Name :	Bottom Ash Pond	Owner:	Cleco Power LLC
Surface Impoundment ID:	P-0005-R1	Operator:	Cleco Power LLC
Nearest City:	Boyce	Parish:	Rapides
Inspector:		Gary J. Leonards, P.E.	
Company:		Providence Engineering & Environmental Group LLC	
Date of Inspection:		12/16/2024	
Weather at Time of Inspection:		Mostly Cloudy, Cool	
DESCRIPTION OF THE OPERATION OF THE SURFACE IMPOUNDMENTS:			
<p>The Brame Energy Center's Bottom Ash surface impoundment is designed to accept the coal combustion residual (CCR) byproducts derived from burning of the Unit 2 coal for the generation of electricity. The Bottom Ash pond is classified by the Louisiana Department of Environmental Quality (LDEQ) as Type I Surface Impoundment. Stormwater and sluice water accumulated in the Bottom Ash Pond is discharged by means of three pumps that discharge the wastewater through the outlet pipe on the western end of the pond. This water discharges into Lake Rodemacher via LPDES outfall 401, thence to Bayou Jean de Jean via LPDES outfall 001, then to the Red River. The minimum levee elevation for the Bottom Ash impoundment is 106 feet NAVD 88. To determine the maximum storage capacity, Providence assumed a freeboard of three feet to the top of the impoundment. The bottom elevation of the Bottom Ash Pond as noted in the solid waste permit application is 85 feet MSL. The maximum capacity of this impoundment, with a freeboard of three feet, is approximately 760.5 acre-feet.</p>			
1.0 GENERAL INFORMATION			
Owner Contact:	Kasey Moore	Phone:	318-793-1194
Director-Brame Energy Center:	Chris Estes	Phone:	318-793-1200
Dam Status:	Operational	Year Built:	1982
Latitude:	31° 23.83' N	Longitude:	92° 42.27' W
Dam Size:	760.5 Acre-Feet (3' Freeboard)		
Bottom of Pond Elevation Information:	85 ft. MSL	Top of Dike Elevation:	106 ft. NAVD 88
Low Operating Level Elevation:	90 ft. NAVD 88	High Operating Level Elevation:	96 ft. NAVD 88
High Operating Level Storage:	464.75 acre-feet @ elevation 96.0 ft. NAVD 88		
Maximum Storage:	760.5 acre feet @ elevation 103.0 ft. NAVD 88		
Maximum Surface Impoundment Area:	45.80 Acres		
Offsite Drainage Area:	Discharges to Lake Rodemacher via LPDES Outfall 401		
Spillway Type:	None, Pumped through HDPE discharge pipe		

SECTION 2.0

QUESTIONS FOR OWNER'S REPRESENTATIVE

2.0 QUESTIONS FOR OWNER'S REPRESENTATIVE	
Construction Plans Available?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Site Facility Map Available?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Operations and Maintenance Manual Available?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Emergency Action Plan Available?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Recent Modification or Improvements?	N/A
Are Routine Inspections Completed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Is Routine Maintenance Completed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Is There Vehicle Access to the Pond?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Is Access Available During Heavy Rains?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Are Routine Inspection Logs Kept On-site?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Offsite Drainage Area:	Discharges to Lake Rodemacher via LPDES Outfall 401.
Spillway Type:	None, Pumped through discharge pipe.

SECTION 3.0

PHYSICAL DAM FEATURES - RESERVOIR

3.0 PHYSICAL DAM FEATURES – RESERVOIR:	
Staff Gauge Type:	Level Gauge Indicator
Staff Gauge Elevation at Time of Inspection:	Not observed
Normal Operating Elevation:	92.0 ft. NAVD 88
Typical Operation:	Discharges to Lake Rodemacher via LPDES Outfall 401.
Are there any visible swirls?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size, location, etc.)	
Is there excessive CCR buildup in the surface impoundment?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Approximate volume of Impounded water at time of inspection:	485 acre-feet
Approximate volume of CCR at time of inspection:	150,000 cubic yards
Findings:	The reservoir was inspected and appeared to be in satisfactory condition.
Other observations on the reservoir:	None

SECTION 4.0

PHYSICAL DAM FEATURES - INTAKE WORKS

4.0 PHYSICAL DAM FEATURES – INTAKE WORKS:	
Number of Intakes:	Five
Description (1):	Primary Bottom Ash Sluice Pipe
Size and Type:	12 Inch Steel Pipe
Control:	Controlled by Pumps at Plant
Can Flow be Shutoff or Bypassed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Description (2):	Secondary Bottom Ash Sluice Pipe
Size and Type:	12 Inch HDPE Pipe
Control:	Controlled by Pumps at Plant
Can Flow be Shutoff or Bypassed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Description (3):	Boiler Area Storm water Sump Pipe
Size and Type:	12 Inch Steel Pipe
Control:	Controlled by Pumps at Plant
Can Flow be Shutoff or Bypassed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Description (4):	Fly Ash Discharge Pipe into Bottom Ash Pond
Size and Type:	6 inch HDPE Pipe
Control:	Controlled by Pump from Fly Ash Pond
Can Flow be Shutoff or Bypassed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Description (5):	Bottom Ash Sluice Trench Stormwater Pipe
Size and Type:	24 inch corrugated metal pipe
Control:	None
Can Flow be Shutoff or Bypassed:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Is the in-flow piping free of debris and otherwise unobstructed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
If no, describe (type of debris, reason for obstruction, etc.)	
Describe the quality of discharge from hydraulic structure (turbidity, depth, etc.)	The inflowing water contains bottom ash which is sluiced out of solution.
Findings:	The intake works were inspected and appeared to be in satisfactory condition. No corrective actions are required at this time.
Other observations on the intake works:	None

SECTION 5.0

PHYSICAL DAM FEATURES - OUTLET WORKS

5.0 PHYSICAL DAM FEATURES – OUTLET WORKS:	
Number of Outlets:	One
Outlets/Culvert Pipe Sizes:	12 Inches
Type of Pipes:	HDPE Pipe that runs through 24 inch CMP
Control:	Pump level controls
Can Flow be Shutoff or Bypassed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Describe the overall condition of the hydraulic structure: (Check all that apply)	<input checked="" type="checkbox"/> Functioning Normally <input type="checkbox"/> Not Functional <input type="checkbox"/> Deteriorated <input type="checkbox"/> Damaged <input type="checkbox"/> Adequate <input type="checkbox"/> Inadequate Other:(describe)
Is there evidence of erosion around the hydraulic structure?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Is the hydraulic structure outlet flowing freely and unobstructed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
If no, describe (type of debris, reason for obstruction, etc.)	
Describe the quality of discharge from the hydraulic structure (turbidity, depth, etc.)	The outflowing water is relatively clear and discharges to Lake Rodemacher via LPDES Outfall 401 which cycles back to the plant.
Findings:	The outlet works were inspected and appeared to be in satisfactory condition. No corrective actions are required at this time.
Other observations on the outlet works:	None

SECTION 6.0

SLOPE PROTECTION - EXTERIOR SLOPES

6.0 SLOPE PROTECTION – EXTERIOR SLOPES:	
Describe the vegetation on the exterior slope: (Check all that apply)	<input type="checkbox"/> Recently Mowed <input checked="" type="checkbox"/> Good Cover <input type="checkbox"/> Sparse <input type="checkbox"/> Other: (describe)
Is there any erosion on the exterior slope?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Is there any erosion protection on the exterior slopes? (e.g. riprap, other)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (riprap - adequate, inadequate, etc.)	
Are there any Crack/Rills Observed?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Are there any Sinkholes Observed?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Are there any trees on the slopes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (type of vegetation, size, location, etc.)	
Findings:	The exterior slope was inspected and appeared to be in satisfactory condition.
Other observations on the exterior slopes:	None

SECTION 7.0

SLOPE PROTECTION - INTERIOR SLOPES

7.0 SLOPE PROTECTION – INTERIOR SLOPES:	
Describe the vegetation on the interior slopes: (Check all that apply)	<input type="checkbox"/> Recently Mowed <input checked="" type="checkbox"/> Good Cover <input type="checkbox"/> Sparse <input type="checkbox"/> Other: (describe)
Is there any erosion on the interior slope?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Is there any erosion protection on the interior slopes? (e.g. riprap, other)	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
If yes, describe what type and it's condition (riprap - adequate, inadequate, etc.) Riprap at 24" CMP storm water pipe outlet. Protection is adequate.	
Are there any Crack/Rills Observed?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Are there any Sinkholes Observed?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Findings:	The interior slope was inspected and appeared to be in satisfactory condition. There is excessive vegetation on the interior of the west slope adjacent to Cell 4 of the landfill. Also, there is erosion that needs to be addressed on the interior of the west slope near where the sluice lines go under the roadway between the landfill and the Bottom Ash Pond.
Other observations on the interior slopes:	None.

SECTION 8.0

SLOPE PROTECTION - ABUTMENT/TOE

8.0 SLOPE PROTECTION – ABUTMENT/TOE:	
Describe the vegetation on the Abutment/Toe: (Check all that apply)	<input type="checkbox"/> Recently Mowed <input checked="" type="checkbox"/> Good Cover <input type="checkbox"/> Sparse <input type="checkbox"/> Other: (describe)
Is there any erosion on the abutment/toe?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Is there any erosion protection on the abutment/toe? (e.g. riprap, other)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe what type and it's condition (riprap - adequate, inadequate, etc.)	
Are there any Crack/Rills Observed?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Is there any Seepage Observed:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size of area, location, severity, etc.)	
Findings:	The abutment/toe was inspected and appeared to be in satisfactory condition. No corrective actions are required at this time.
Other observations on the abutment/toe:	None

SECTION 9.0
SURFACE IMPOUNDMENT CREST

9.0 SURFACE IMPOUNDMENT CREST:	
Describe the vegetation on the crest: (Check all that apply)	<input type="checkbox"/> Recently Mowed <input checked="" type="checkbox"/> Good Cover <input type="checkbox"/> Sparse <input checked="" type="checkbox"/> Other: (describe) Gravel
Is there a road or driveway on the crest?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
If yes, describe (good condition, numerous cracks, etc.) Good Condition	
Are there any ruts, depressions, or holes on the crest?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size, location, etc.)	
Are there any cracks on the crest?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (length and width, location and direction of cracking, etc.)	
Are there any trees or other undesired vegetation on the crest?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size, location, etc.)	
Are there any sinkholes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If yes, describe (size, location, etc.)	
Findings:	The crest was inspected and appeared to be in satisfactory condition. No corrective actions are required at this time.
Other observations on the crest:	None

SECTION 10.0

PHYSICAL DAM FEATURES - SPILLWAY

10.0 PHYSICAL DAM FEATURES – SPILLWAY:	
Type:	None - Pumped through discharge pipe
Slope Protection:	NA
Approach:	NA
Erosion:	NA
Vegetation:	NA
Findings:	NA
Other observations on the spillway:	NA

SECTION 11.0

DOCUMENTATION REVIEW

11.0 DOCUMENTATION REVIEW:	
Weekly Inspections Reviewed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Findings: Weekly inspection documentation needs to be organized for ease of review.	
Monthly Instrument Inspections Reviewed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Findings: No Issues.	
Groundwater Monitoring:	Monitoring wells are in-place for routing monitoring.
Drawings Reviewed:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Are there any changes in the geometry of the surface impoundment structure since the previous inspection?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> NA
If yes, describe (size, location, etc.)	
Other observations:	None

APPENDIX A
PHOTOGRAPH LOG

Site Name: Brame Energy Center – Bottom Ash Pond

Site Location: Lena, Rapides Parish, LA

Date: December 16, 2024

Bottom Ash Pond

Direction:

South

Comments:

Pond discharge structure



Bottom Ash Pond

Direction:

Northeasterly

Comments:

North levee slope



Site Name: Brame Energy Center – Bottom Ash Pond

Site Location: Lena, Rapides Parish, LA

Date: December 16, 2024

Bottom Ash Pond

Direction:

Southeasterly

Comments:

Southern facing
overview



Bottom Ash Pond

Direction:

Southeasterly

Comments:

Eastern levee
exterior slope



Site Name: Brame Energy Center – Bottom Ash Pond

Site Location: Lena, Rapides Parish, LA

Date: December 16, 2024

Bottom Ash Pond

Direction:

Southeasterly

Comments:

Eastern levee inside slope



Bottom Ash Pond

Direction:

Northwesterly

Comments:

Eastern levee outside slope



Site Name: Brame Energy Center – Bottom Ash Pond

Site Location: Lena, Rapides Parish, LA

Date: December 16, 2024

Bottom Ash Pond

Direction:

Northwesterly

Comments:

Eastern levee,
inside slope



Bottom Ash Pond

Direction:

Southwesterly

Comments:

South levee, inside
slope



Site Name: Brame Energy Center – Bottom Ash Pond

Site Location: Lena, Rapides Parish, LA

Date: December 16, 2024

Bottom Ash Pond

Direction:

Southeasterly

Comments:

Excess vegetation on the west slope of the Bottom Ash Pond



Bottom Ash Pond

Direction:

Northeasterly

Comments:

Erosion on the west slope that needs addressing



APPENDIX B
P.E. CERTIFICATION

**BOTTOM ASH POND
CCR ANNUAL INSPECTION**

PROFESSIONAL ENGINEER CERTIFICATION

I hereby certify that I have inspected Cleco's Brame Energy Center Bottom Ash Pond in accordance with the Annual CCR Inspection requirements. This inspection has determined that the design, operation, and maintenance of the Bottom Ash Pond is in accordance with generally accepted engineering standards and are adequate for the facility.

Gary J. Leonards, P. E.

Name

30568

Registration No.


LA

State

Signature

01/17/25

Date



(Seal)

This inspection was conducted to assess the general overall condition of the reservoir/dam, identify visible deficiencies, and recommend areas for monitoring, and corrective actions. The inspection is based only on visible features/areas of the dam on the day of inspection. The owner should verify the findings of this report and take corrective actions. This inspection does not relieve the owner/operator from their responsibility to conduct routine inspections, maintenance, repairs, modifications, monitoring, and documentation.