

Obs_DateTime	Obs_ObserverFormattedName	Line of Business	Hazard Identification Location	Obs Type	Hazard Short Description	Potential Hazards	Hazard Detailed Description	Able to Correct or Mitigate	Corrective or Mitigation Methods	Work Order Created	Work Order Number	Follow Up Requested
Dec 11, 2023 3:34:00 PM	Employee Name and Number	Transmission/Distribution	PVSC		Bypassed Recloser	Electrical - Arc Flash	Contractors placed three single phase reclosers on one shot so that they could receive an energized safety document from the DOC. Document was issued and contractors began to work. Another contractor who was consulting on the job rode by the single phase reclosers and noticed that one of them was bypassed.	Yes	The contractor who identified the problem contacted the DOC and requested a new one shot be given on the next upline device while operations investigated why the recloser was bypassed.	N/A		No
Dec 11, 2023 11:05:00 PM	Employee Name and Number	Support	BCIPP			Gravity - Suspended Load, Motion - Mobile Equipment and Workers on Foot, Mechanical - Heavy Rotating Equipment, Temperature - Steam, Pressure - Explosion, Electrical - Electrical Contact with Source, Chemical / Radiation - High Dose of Toxic Chemical or Radiation, Gravity - Fall from Elevation, Motion - Motor vehicle incident (occupant), Temperature - High Temperature, Temperature - Fire with Sustained Fuel Source, Pressure -		No		N/A		No